



1750 4375 1250
 2300
 -0,150
 2150 2200
 440 440
 6505
 300 4000 2360 1975 115
 115 1795 2400 440
 700 1970 750(1550)
 1375 500
 1250 2300 11500
 -0,150
 800 1970 800 1970 115 115
 1.05 LOŽNICE 1.04 ŠATNA
 4000 4000
 2985 115 2810 440
 440 440
 1750 2260 115 2000 1250
 13000 1000 (1300) 1000 (1300)
 -0,600